

Job Number	SIO-119323	Vehicle Registration	EY72WRT	Operator	Warton Freight Services Ltd
Inspection Date	06/09/2025	Make / Model	PALFINGER / PK37.002ATEC7	Serial Number	1100083315
Service Type	Thorough Inspection	Chassis Number	P186922	Mileage	88401

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

REPORT OF THOROUGH EXAMINATION AND TEST OF LIFTING PLANT AND EQUIPMENT

Record No.:- SIO-119323		Date of last examination:- 07/09/24		Record No. of last examination:- SIO-101880																																											
Description of equipment, including year of manufacture:- PALFINGER / PK37.002ATEC7 2022 / EY72WRT																																															
Identification mark of the equipment:- 1100083315																																															
Name and address of owner of equipment, and its location:- Warton Freight Services Ltd, 15 Horndon Industrial Park, Station Road, West Horndon, CM13 3XL			Address where examination and test carried out if different to owner:- Warton Freight Services Ltd, 15 Horndon Industrial Park, Station Road, West Horndon, CM13 3XL, 0181 5073354																																												
Reason for Test	Commissioning ☐ LOLER Reg 6	6 Month ☐ LOLER Reg 9.3.a.(i)	12 Month ☒ LOLER Reg 9.3.a.(ii)	Overload Test ☐ BS7121 Part 2-4	Exceptional Circumstances ☐ LOLER Reg 9.3.a.(iv)																																										
<table border="0" style="width: 100%;"> <tr> <td colspan="3">Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-</td> <td colspan="3">Rated capacity (KG)</td> </tr> <tr> <td colspan="3">Radius (Outreach) M</td> <td colspan="3"></td> </tr> <tr> <td colspan="3">4.4</td> <td colspan="3">7400</td> </tr> <tr> <td colspan="3">6.2</td> <td colspan="3">5200</td> </tr> <tr> <td colspan="3">8.1</td> <td colspan="3">3900</td> </tr> <tr> <td colspan="3">10.2</td> <td colspan="3">3050</td> </tr> <tr> <td colspan="3">12.3</td> <td colspan="3">2500</td> </tr> </table>						Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-			Rated capacity (KG)			Radius (Outreach) M						4.4			7400			6.2			5200			8.1			3900			10.2			3050			12.3			2500		
Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-			Rated capacity (KG)																																												
Radius (Outreach) M																																															
4.4			7400																																												
6.2			5200																																												
8.1			3900																																												
10.2			3050																																												
12.3			2500																																												
<table border="0" style="width: 100%;"> <tr> <th colspan="5">Details of the test or test carried out:-</th> </tr> <tr> <td>Radius (Outreach) M</td> <td>Rated Capacity (KG)</td> <td>Test Percentage</td> <td>Test Weight (KG)</td> <td>Has the Weight Been Applied</td> </tr> <tr> <td>12.3</td> <td>2500</td> <td>10%</td> <td>2750</td> <td>Yes</td> </tr> </table> CRANE TESTED ON FIRM LEVEL SURFACE WITH ALL OUTRIGGER LEGS FULLY DEPLOYED						Details of the test or test carried out:-					Radius (Outreach) M	Rated Capacity (KG)	Test Percentage	Test Weight (KG)	Has the Weight Been Applied	12.3	2500	10%	2750	Yes																											
Details of the test or test carried out:-																																															
Radius (Outreach) M	Rated Capacity (KG)	Test Percentage	Test Weight (KG)	Has the Weight Been Applied																																											
12.3	2500	10%	2750	Yes																																											
Identification of any part found to have a defect which is, or could become a danger to persons. The particulars of any repair, renewal or alteration required to remedy the defect either immediately or within a specified time:-																																															
Other defects and remedies:- N/A																																															
Observation and condition of attachment (where applicable):-																																															
Declaration:- I hereby declare that the equipment described in this record was tested, or tested and thorough examined in accordance with the Lifting Operations and Lifting Equipment Regulations (LOLER) 1998 and the above particulars are correct.																																															
																																															
Signature:-			Date the examination and test or test only carried out:- 06/09/2025																																												
Name and address of examiner / person making above declaration where applicable:-																																															
pmalinowski ALLMI Registration Number:- T H White Ltd, Nursteed Road, Devizes, Wiltshire, SN10 3EA			ALLMI Registration Number:- T H White Ltd, Trevor Foster Way, Off Chase Way, Bradford, West Yorkshire, BD5 8HB																																												
Name of person making above declaration (only to be completed if different from examiner):-																																															
ALLMI Registration Number:-																																															
Date of initial Commissioning Test:- 22/07/2022		Latest Date by which next thorough examination must be carried out:- 06/09/2026																																													
Date the record is made:- 06/09/2025		Latest Date by which next BS7121 overload test must be carried out:- 22/07/2026																																													

Job Number	SIO-119323	Vehicle Registration	EY72WRT	Operator	Warton Freight Services Ltd
Inspection Date	06/09/2025	Make / Model	PALFINGER / PK37.002ATEC7	Serial Number	1100083315
Service Type	Thorough Inspection	Chassis Number	P186922	Mileage	88401

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Check	J
Pre-Inspection Requirements		
1.1	Equipment Clean & Ready for Inspection: Yes	✓
1.2	Copy of Previous Report of Thorough Examination: Yes	✓
1.3	Copy of Stability Calculation: Yes	✓
1.4	Copy of Operators Manual: Yes	✓
1.5	Record Equipment Mounting Position: Front Mount	✓
1.6	Hour Meter Reading Taken and Recorded: Yes; 608	✓
Information Plates		
2.1	SWL Plates / Decals	✓
2.2	Operator Hazard Warning Plates	✓
2.3	Equipment C E / Serial Plate	✓
Pump / PTO		
3.1	PTO Switch / Interlock	✓
3.2	Air Tee / Contact Switch	✓
3.3	PTO Unit	✓
3.4	Pump	✓
3.5	Oil Tank	✓
3.6	Hydraulic Oil	✓
3.7	Pressure Feed Hose	✓
3.8	High Pressure Filter	✓
3.9	Suction Hose, Clamps & Protection	✓
3.10	Diverter Valve	✓
3.11	Power on Demand / RPM / Auto Throttle	✓
3.12	Equipment Operation	✓
Subframe / Crane Base		
4.1	Subframe Fabrication & Condition	✓
4.2	Subframe C.E. Plate	✓
4.3	Side Plate / Droppers	✓
4.4	Crane Base Structure	✓
4.6	Pendulum Beam	✓
4.7	Hold Down Fixings	✓
4.8	Slew Tubes	✓
4.9	Slewing System - Slew Tube Type	✓
4.10	Slewing System LHV	✓
Outrigger Legs (Including Additional Outrigger Legs if Applicable)		
5.1	Beam Structure	✓
5.2	Rollers / Wear Pads	✓
5.3	Cam Locks and R Clips	✓
5.5	Leg Stops	✓
5.6	Stabilizer Leg Sensors / Switches	✓
5.7	Stability Control Sensors / Switches	✓
5.8	Hoses / Pipes, Clamps & Protection	✓
5.9	Stabilizer in / out Leg Cylinder	✓
5.11	Pivoting Stabilizer Feet	✓
5.12	Stabilizer Cylinders	✓
5.13	Swing Up Stabilizer	✓
5.14	Stabilizer Operation	✓

Job Number	SIO-119323	Vehicle Registration	EY72WRT	Operator	Warton Freight Services Ltd
Inspection Date	06/09/2025	Make / Model	PALFINGER / PK37.002ATEC7	Serial Number	1100083315
Service Type	Thorough Inspection	Chassis Number	P186922	Mileage	88401

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Check	J
5.15	■ Stabilizer Support Pads & Stowage Cage	✓
Valve Block(s)		
6.1	■ Dump Valve	✓
6.2	■ Valve Segment Port Relief Seals	✓
6.3	■ Overload Valve (OSK) Seals	✓
6.4	■ Main Relief Valve Seals	✓
6.5	■ Valve Block	✓
6.6	■ Control Levers / Rods	✓
6.7	■ Control Lever Decals	✓
6.8	■ Additional Valve Block	✓
6.9	■ Additional Valve Block Control Levers / Rods	✓
6.10	■ Additional Valve Block Control Lever Decals	✓
6.11	■ Pressure Gauge / Fittings	✓
Column		
7.1	■ Column Structure	✓
7.2	■ Neck & Foot Bearings	✓
7.3	■ Hoses / Pipes, Clamps & Protection	✓
7.4	■ Pins / Bushes / Retainers	✓
7.5	■ Continual Slew System	✓
Main (Inner) Boom Cylinder		
8.1	■ Main Boom Cylinder	✓
8.3	■ Load Hold Valve	✓
8.4	■ Pressure Transducer	✓
8.5	■ Pin / Bushes / Retainers	✓
8.6	■ Hoses / Pipes, Clamps & Protection	✓
Main (Inner) Boom		
9.1	■ Main Boom Structure	✓
9.2	■ Hoses / Pipes, Clamps & Protection	✓
9.3	■ Pins / Bushes / Retainers	✓
9.4	■ Boom Geometry Encoder	✓
Jib (Outer) Boom Cylinder		
10.1	■ Outer Boom Cylinder	✓
10.3	■ Load Hold Valve	✓
10.4	■ Pins / Bushes / Retainers	✓
10.5	■ Hoses / Pipes, Clamps & Protection	✓
Outer (Jib) Boom		
11.1	■ Outer Boom Structure	✓
11.2	■ Hoses / Pipes, Clamps & Protection	✓
11.3	■ Pins / Bushes / Retainers	✓
11.4	■ Boom Geometry Encoder	✓
11.5	■ Pendulum Switch	✓
Extension System		
12.1	■ Boom Structure (s)	✓
12.2	■ Cylinder(s)	✓
12.3	■ Load Hold Valve	✓
12.4	■ Sequence Valve	✓
12.5	■ Cylinder Guides	✓

Job Number	SIO-119323	Vehicle Registration	EY72WRT	Operator	Warton Freight Services Ltd
Inspection Date	06/09/2025	Make / Model	PALFINGER / PK37.002ATEC7	Serial Number	1100083315
Service Type	Thorough Inspection	Chassis Number	P186922	Mileage	88401

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Check	J
12.6	■ Wear Pads / Retaining Screws	✓
12.7	■ Pins / Bushes	✓
12.10	■ Hoses / Pipes, Clamps & Protection	✓
Lifting Hook		
13.1	■ Hook Assembly	✓
13.2	■ D Shackle and Pin	✓
Safe Stowage System		
14.1	■ Boom Height Warning	✓
14.2	■ Boom Height Decal: 12 feet 4 inches	✓
14.3	■ Crane Stowage Warning	✓
14.4	■ Stabilizer Legs Stowage Warning	✓
Other Safety Equipment		
15.1	■ Leg Deployment	✓
15.2	■ Derate System	✓
15.6	■ Safety Equipment Decals	✓
15.7	■ Vehicle Level Indicators	✓
Electrics		
16.1	■ Paltronic Display	✓
16.2	■ Additional Display(s)	✓
16.3	■ Additional Emergency Stop(s)	✓
16.4	■ OLP (Overload Protection) System	✓
16.5	■ Beacons	✓
16.6	■ Work Lights	✓
16.7	■ Hydraulic Oil Cooler	✓
Radio Remote Control		
17.1	■ RRC Handset	✓
17.2	■ RRC Display	✓
17.3	■ RRC Operation	✓
17.4	■ RRC Active Warning Beacon	✓
17.5	■ Emergency Stop	✓
17.6	■ OLP System (Overload Protection System)	✓
17.7	■ Work Light Switch	✓
17.9	■ AOS (Active Oscillation Suppression)	✓
17.10	■ Warning Horn	✓
17.11	■ RRC Neck / Lap Belt	✓
17.12	■ RRC Handset Stowage System	✓
17.13	■ Programming Lead	✓
17.14	■ Decals	✓
Further Actions		
46.1	■ Service 1000 Hour Counter Reset?: Yes	✓
46.2	■ Post Weight Test Inspection Complete?: Yes	✓
46.4	■ Decal for next Service Inspection or Service Inspection and Weight Test completed?: Yes	✓
46.6	■ Equipment Safe for Use?: Yes	✓

Service

Job Number SIO-119323

Vehicle Registration EY72WRT

Operator Warton Freight Services Ltd

Inspection Date 06/09/2025

Make / Model PALFINGER / PK37.002ATEC7

Serial Number 1100083315

Service Type Thorough Inspection

Chassis Number P186922

Mileage 88401

Judgement key (J)

 / ✓ = Satisfactory

 / M = Monitored

 / R = Requires attention

I hereby declare that the equipment described in this record was tested, or tested and thorough examined in accordance with the Lifting Operations and Lifting Equipment Regulations (LOLER) 1998 and the appropriate provisions and the above particulars are correct.



Name: pmalinowski

Date: 06/09/2025