

REPORT OF THOROUGH EXAMINATION

As required by The Lifting Operations and Lifting Equipment Regulations (LOLER) 1998

DATE: 2nd January 2026

TEST NUMBER: 2601001

LOADER MAKE: Fassi

TYPE: F545RA.2.26 xe-dynamic

SERIAL NUMBER: 5450-1179 (2024)

Stabilizer/s Spread: Loader (m) 7.79 Supplementary (m) 5.0

Note: Rated capacities quoted below only apply with stabilizer/s set in above operating condition fully extended and down on firm level ground.

Specific operating conditions:

To achieve a full capacity lift legs should be fully extended and down on firm level ground. Operation of loader is restricted by FSC/SII stability control system. Operation of loader forward of front stabilizers is restricted by LML device in accordance with vehicle stability. Air suspension and tag axle must be lowered before use.

Name and address of lorry loader owner:

Warton Freight Services
15 Horndon Industrial Park Station Road West Horndon Essex CM13 3XL

Lorry loader mounting details:

Front mount
Volvo FH

Reg. No: KR74 CLO

Chassis No:

Reason for test: Annual LOLER 9.3.a (ii)

Rated capacities and overloads applied: See below

RADIUS (m)	TEST LOAD (kg) 10%	RATED CAPACITY (kg)
6.40	-	7080
10.15	-	4200
14.25	-	2880
16.30	2750	2500

Note: Adjacent rated capacities include any hook, attachments, slings, chains, etc. i.e. the weight of the hook, attachments, slings, etc. must be included as part of the load.

Defects noted and alterations or repairs required before loader is put into service: None
(service sheet 156364)

Date of the previous test and examination: 3rd January 2025

Latest date by which the next examination must be carried out: 1st January 2027

I hereby certify that the lorry loader described in this certificate was tested and examined on 2nd January 2026 and that the above particulars are correct.

Name of tester:

 K. Mumford

Authorised tester

Authorised Signature:

For and on behalf of Walker Crane Services Limited
Hainault Trading Estate, Motherwell Way, Grays, Essex, RM20 3XD
E&OE
Form F11

V2

20/09/18