




REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 28TH FEBRUARY 2026		DATE OF REPORT 28TH FEBRUARY 2026		REPORT NUMBER 2026/INS1532		ASSET / REG NUMBER EK19 VAX		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				☒ YES ☐ NO		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY? ☐ YES ☒ NO			
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				☒ 6 MONTHLY EXAMINATION ☐ 12 MONTHLY EXAMINATION		☒ EXAMINATION SCHEME ☐ EXCEPTIONAL OCCURRENCE			
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
CONTAINER BOTTOM LIFTER			YES	WF053	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF054	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF055	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF056	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF024	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF025	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF026	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
CONTAINER BOTTOM LIFTER			YES	WF027	12.5 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons ☒ YES ☐ NO ☐ X			
						Is the above defect which is not yet but could become a danger to persons ☐ YES ☐ NO ☐ X			
						(If YES state the date by when) YES by:			
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT			SIGNATURE OF AUTHENTICATOR			
C WALLACE			C WALLACE			C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 28TH FEBRUARY 2026		DATE OF REPORT 28TH FEBRUARY 2026		REPORT NUMBER 2026/INS1532		ASSET / REG NUMBER EK19 VAX		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO		X		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?	
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X		EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
4 LEG, 6 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA GRADE 8			YES	3567625	6.7 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
4 LEG, 4 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 7MM DIA GRADE 8			YES	LT03778/1	3.1 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
2 LEG, 1.5 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA GRADE 8			YES	LE1153/80	4.25 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
1 LEG, 1 MTR CHAIN SLING C/W SHORTENER & SELF LOCKING SAFETY HOOK X 13MM DIA			YES	LTR0424/1	5.3 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES NO X	
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT C WALLACE			NAME OF PERSON AUTHENTICATING REPORT C WALLACE			SIGNATURE OF AUTHENTICATOR C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 28TH FEBRUARY 2026		DATE OF REPORT 28TH FEBRUARY 2026		REPORT NUMBER 2026/INS1532		ASSET / REG NUMBER EK19 VAX		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO		X		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?	
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X		EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
2 MTR DUPLEX WEBBING SLING			YES	82218243	2.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	82218244	2.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	250403768	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	250403769	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	250358400	2.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	251003136	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	251003138	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	251003142	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	251003145	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	250503161	2.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	250503163	2.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	250711809	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES NO X	
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT C WALLACE			NAME OF PERSON AUTHENTICATING REPORT C WALLACE			SIGNATURE OF AUTHENTICATOR <i>C Wallace</i>			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION		DATE OF REPORT		REPORT NUMBER		ASSET / REG NUMBER		PAGE NUMBER		
28TH FEBRUARY 2026		28TH FEBRUARY 2026		2026INS1532		EK19 VAX		2		
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO	X	IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?			YES NO	X
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X	EXAMINATION SCHEME		X	EXCEPTIONAL OCCURRENCE
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT				
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR				
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT	
6 MTR DUPLEX WEBBING SLING			YES	250911817	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
4 MTR DUPLEX WEBBING SLING			YES	235509006	3.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL	
4 MTR DUPLEX WEBBING SLING			YES	240838121	3.0 TON	UNKNOWN	28/02/2026	27/08/2026	VISUAL	
6 MTR DUPLEX WEBBING SLING			YES	251018189	3.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
6 MTR DUPLEX WEBBING SLING			YES	251018190	3.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
6 MTR DUPLEX WEBBING SLING			YES	251018191	3.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
6 MTR DUPLEX WEBBING SLING			YES	251018193	3.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
10 MTR DUPLEX WEBBING SLING			YES	92443298	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
10 MTR DUPLEX WEBBING SLING			YES	92443335	2.0 TON	NEW ISSUE	28/02/2026	27/08/2026	VISUAL	
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE										
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES	NO	X
						Is the above defect which is not yet but could become a danger to persons				
						(If YES state the date by when)		YES by:		
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT										
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT				SIGNATURE OF AUTHENTICATOR			
C WALLACE			C WALLACE				C Wallace			