


REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998


DATE OF THOROUGH EXAMINATION 18TH JULY 2026		DATE OF REPORT 18TH JULY 2026		REPORT NUMBER 2026INS1689		ASSET / REG NUMBER EY25 VZZ		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				☒ YES ☐ NO		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY? ☐ YES ☐ NO			
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				☐ 6 MONTHLY EXAMINATION ☐ 12 MONTHLY EXAMINATION		☒ X EXAMINATION SCHEME		☒ X EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
4 LEG, 6 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA G8			YES	EHCS539	6.7 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
4 LEG, 6 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 7MM DIA G8			YES	LTR426/6C	3.1 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
2 LEG, 1.5 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 13MM DIA G8			YES	LE351-3A	7.5 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
1 LEG, 1.5 MTR CHAIN SLING C/W SELF LOCKING SAFETY HOOK X 13MM DIA G8			YES	DC156	5.3 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES	NO
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT			SIGNATURE OF AUTHENTICATOR			
C.WALLACE			C.WALLACE			C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 18TH JULY 2026		DATE OF REPORT 18TH JULY 2026		REPORT NUMBER 2026INS1689		ASSET / REG NUMBER EY25 VZZ		PAGE NUMBER 2		
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO	X	IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?			YES NO	X
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X	EXAMINATION SCHEME	X	EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR				
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT	
1 LEG, 1.5 MTR CHAIN SLING C/W SHORTENER & SELF LOCKING SAFETY HOOK X 10MM DIA G8			YES	TLG021605	3.15 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL	
1 LEG, 1.5 MTR CHAIN SLING C/W SHORTENER & SELF LOCKING SAFETY HOOK X 10MM DIA G8			YES	TLG021606	3.15 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL	
1 LEG, 1.5 MTR CHAIN SLING C/W SHORTENER & SELF LOCKING SAFETY HOOK X 10MM DIA G8			YES	TLG021607	3.15 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL	
1 LEG, 1.5 MTR CHAIN SLING C/W SHORTENER & SELF LOCKING SAFETY HOOK X 10MM DIA G8			YES	TLG021608	3.15 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL	
2 LEG, 3.5 MTR CHIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA G8			YES	WP759	4.25 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL	
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE										
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES	NO	X
						Is the above defect which is not yet but could become a danger to persons				
						(If YES state the date by when)		YES by:		
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT										
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT C.WALLACE			NAME OF PERSON AUTHENTICATING REPORT C.WALLACE			SIGNATURE OF AUTHENTICATOR <i>C Wallace</i>				



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 18TH JULY 2026		DATE OF REPORT 18TH JULY 2026		REPORT NUMBER 2026INS1689		ASSET / REG NUMBER EY25 VZZ		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				☒ YES ☐ NO		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY? ☐ YES ☐ NO			
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				☐ 6 MONTHLY EXAMINATION ☐ 12 MONTHLY EXAMINATION		☒ X EXAMINATION SCHEME		☒ X EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESBIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
2 MTR DUPLEX WEBBING SLING			YES	235507144	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	235507139	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	231251063	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
2 MTR DUPLEX WEBBING SLING			YES	062206809	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	SFH007589	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	SFH007584	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	235581868	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	235581865	2.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	230347260	3.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	230347265	3.0 TON	UNKNOWN	18/07/2026	17/01/2027	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES	NO
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT				SIGNATURE OF AUTHENTICATOR		
C WALLACE			C WALLACE				C Wallace		



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION		DATE OF REPORT		REPORT NUMBER		ASSET / REG NUMBER		PAGE NUMBER	
18TH JULY 2026		18TH JULY 2026		2026INS1689		EY25 VZZ		2	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO	X	IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?			YES NO
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X	EXAMINATION SCHEME		X
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE				ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT		
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL				WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESBIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR		
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED				SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION
3 MTR DUPLEX WEBBING SLING				YES	25/5074378	3.0 TON	UNKNOWN	18/07/2026	17/01/2027
3 MTR DUPLEX WEBBING SLING				YES	25/5074374	3.0 TON	UNKNOWN	18/07/2026	17/01/2027
6 MTR DUPLEX WEBBING SLING				YES	102413139	3.0 TON	UNKNOWN	18/07/2026	17/01/2027
6 MTR DUPLEX WEBBING SLING				YES	102413166	3.0 TON	UNKNOWN	18/07/2026	17/01/2027
1.5 MTR EWL (3 MTR CIRC) ROUND SLING				YES	11201-010835	2.0 TON	UNKNOWN	18/07/2026	17/01/2027
4 MTR EWL (8 MTR CIRC) ROUND SLING				YES	240636151	2.0 TON	UNKNOWN	18/07/2026	17/01/2027
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE.									
NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above							Is the above defect which is of immediate danger to persons		YES
							Is the above defect which is not yet but could become a danger to persons		NO
							(If YES state the date by when)		YES by:
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load- State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT				NAME OF PERSON AUTHENTICATING REPORT				SIGNATURE OF AUTHENTICATOR	
C WALLACE				C WALLACE				C Wallace	