



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION		DATE OF REPORT		REPORT NUMBER		ASSET / REG NUMBER		PAGE NUMBER	
25TH APRIL 2026		25TH APRIL 2026		2026INS1601		KR74 CLO		1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO		X 		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY? YES NO	
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X 		EXAMINATION SCHEME X EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE		ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE				NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL		WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL				SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED		SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT	
RIGHT HAND BOTTOM LIFTER		YES	WF013	12.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL	
RIGHT HAND BOTTOM LIFTER		YES	WF014	12.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL	
LEFT HAND BOTTOM LIFTER		YES	WF015	12.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL	
LEFT HAND BOTTOM LIFTER		YES	WF016	12.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL	
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE.									
NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above					Is the above defect which is of immediate danger to persons		YES		NO
					Is the above defect which is not yet but could become a danger to persons				
					(If YES state the date by when)		YES by:		
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load- State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT			SIGNATURE OF AUTHENTICATOR			
C WALLACE			C WALLACE			C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 25TH APRIL 2026		DATE OF REPORT 25TH APRIL 2026		REPORT NUMBER 2026/INS1601		ASSET / REG NUMBER KR74 CLO		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO		X		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?	
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X		EXAMINATION SCHEME X EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
2 LEG, 6 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA GRADE 12			YES	25/28857	10.6 TON	UNKNOWN	25/04/2026	26/10/2026	VISUAL
1 LEG, 2 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOK X 10MM DIA GRADE 8			YES	268816-3	3.15 TON	UNKNOWN	25/04/2026	26/10/2026	VISUAL
1 LEG, 2 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOK X 10MM DIA GRADE 8			YES	268816-2	3.15 TON	UNKNOWN	25/04/2026	26/10/2026	VISUAL
1 LEG, 2 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOK X 10MM DIA GRADE 8			YES	268816-4	3.15 TON	UNKNOWN	25/04/2026	26/10/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES NO X	
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT C WALLACE			NAME OF PERSON AUTHENTICATING REPORT C WALLACE			SIGNATURE OF AUTHENTICATOR C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION		DATE OF REPORT		REPORT NUMBER		ASSET / REG NUMBER		PAGE NUMBER	
25TH APRIL 2026		25TH APRIL 2026		2026INS1601		KR74 CLO		2	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES ☒ X NO ☐		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?			YES ☐ NO ☐
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION ☒ X 12 MONTHLY EXAMINATION ☐		EXAMINATION SCHEME		X	EXCEPTIONAL OCCURRENCE
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
1 LEG, 2 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOK X 10MM DIA GRADE 8			YES	LE1715-6	3.15 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
2 LEG, 3 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA GRADE 8			YES	256394-1	4.25 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
2 LEG, 3 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 10MM DIA GRADE 8			YES	256394-2	4.25 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
2 LEG, 1.5 MTR CHAIN SLING C/W SHORTENERS & SELF LOCKING SAFETY HOOKS X 13MM DIA GRADE 8			YES	252531	7.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES ☐	NO ☒ X
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test) IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT			SIGNATURE OF AUTHENTICATOR			
C WALLACE			C WALLACE			C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 25TH APRIL 2026		DATE OF REPORT 25TH APRIL 2026		REPORT NUMBER 2026/INS1601		ASSET / REG NUMBER KR74 CLO		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				☒ YES ☐ NO		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY? ☐ YES ☒ NO			
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				☒ 6 MONTHLY EXAMINATION ☐ 12 MONTHLY EXAMINATION		☒ EXAMINATION SCHEME ☐ EXCEPTIONAL OCCURRENCE			
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
HALFEN LIFTING CLUTCH			YES	S14721	5.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
HALFEN LIFTING CLUTCH			YES	L06919	5.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
HALFEN LIFTING CLUTCH			YES	1116059	2.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
HALFEN LIFTING CLUTCH			YES	Y53	2.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
HALFEN LIFTING CLUTCH			YES	2109	2.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
HALFEN LIFTING CLUTCH			YES	G7111	2.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
BLACK PIN, SCREW PIN ALLOY BOW SHACKLE			YES	K3	6.5 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE. NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons ☒ YES ☐ NO ☐ X			
						Is the above defect which is not yet but could become a danger to persons ☐ YES ☐ NO ☐ X			
						(If YES state the date by when) YES by:			
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT			NAME OF PERSON AUTHENTICATING REPORT			SIGNATURE OF AUTHENTICATOR			
C WALLACE			C WALLACE			C Wallace			



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

DATE OF THOROUGH EXAMINATION 25TH APRIL 2026		DATE OF REPORT 25TH APRIL 2026		REPORT NUMBER 2026INS1601		ASSET / REG NUMBER KR74 CLO		PAGE NUMBER 1	
IS THIS THE FIRST EXAMINATION AFTER INSTALLATION OR AFTER ASSEMBLY AT A NEW SITE OR LOCATION?				YES NO		X		IF THE ANSWER TO THE QUESTION ON THE LEFT IS YES, HAS THE EQUIPMENT BEEN INSTALLED CORRECTLY?	
WAS THE EXAMINATION FOR AN IN SERVICE 6/12 MONTHLY OR FOR AN EXAMINATION SCHEME OR DUE TO AN EXCEPTIONAL OCCURRENCE?				6 MONTHLY EXAMINATION 12 MONTHLY EXAMINATION		X		EXCEPTIONAL OCCURRENCE	
NAME AND ADDRESS OF EMPLOYER FOR WHOM THE THOROUGH EXAMINATION WAS MADE			ADDRESS OF PREMISES AT WHICH THE EXAMINATION WAS MADE			NAME AND ADDRESS OF EMPLOYER OF PERSONS MAKING AND AUTHENTICATING THIS REPORT			
WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			WARTON FREIGHT SERVICES LTD 15 HORNDON INDUSTRIAL PARK STATION ROAD WEST HORNDON ESSEX CM13 3XL			SOUTHEAST LIFTING SERVICES LTD 14A THAMESVIEW CLIFFE WOODS ROCHESTER KENT ME3 8LR			
DESCRIPTION AND IDENTIFICATION OF EQUIPMENT THOROUGHLY EXAMINED			SAFE TO USE	SERIAL No PLANT No. OR BATCH No.	SWL	DATE OF MANUFACTURE (IF KNOWN)	DATE OF THOROUGH EXAMINATION	LATEST DATE FOR NEXT THOROUGH EXAMINATION	DETAILS OF ANY TEST CARRIED OUT
6 MTR DUPLEX WEBBING SLING			YES	23513677	1.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	23513645	1.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	240837084	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	240809464	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	240809381	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
4 MTR DUPLEX WEBBING SLING			YES	251227217	2.0 TON	NEW ISSUE	25/04/2026	24/10/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	235582237	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	240209901	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
8 MTR DUPLEX WEBBING SLING			YES	220217128	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
8 MTR DUPLEX WEBBING SLING			YES	231002173	2.0 TON	UNKNOWN	25/04/2026	24/10/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	251004959	2.0 TON	NEW ISSUE	25/04/2026	24/10/2026	VISUAL
6 MTR DUPLEX WEBBING SLING			YES	251004962	2.0 TON	NEW ISSUE	25/04/2026	24/10/2026	VISUAL
Identification of any part found to have a defect which is or could become a danger to persons and description of defect. If none state NONE.									
NONE									
Particulars of any repair, renewal or alteration required to remedy the defect identified above						Is the above defect which is of immediate danger to persons		YES	NO
						Is the above defect which is not yet but could become a danger to persons			
						(If YES state the date by when)		YES by:	
DETAILS OF ANY TEST CARRIED OUT:- FT (Functional Test) LL (Light Load-State Load Applied) SWL (Safe Working Load) PROOF (Proof Load) NDT (Non Destructive Test)									
IF ANY EQUIPMENT HAS BEEN REPORTED UNSAFE TO USE, PLEASE SEE RELEVANT DEFECT REPORT									
NAME AND QUALIFICATIONS OF PERSON MAKING REPORT C WALLACE			NAME OF PERSON AUTHENTICATING REPORT C WALLACE			SIGNATURE OF AUTHENTICATOR C Wallace			

