

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

REPORT OF THOROUGH EXAMINATION AND TEST OF LIFTING PLANT AND EQUIPMENT

Record No.:- SIO-123217		Date of last examination:- 14/12/24		Record No. of last examination:- SIO-106137																																					
Description of equipment, including year of manufacture:- PALFINGER / PK19.001ASLD5 2019 / EY69YSB																																									
Identification mark of the equipment:- 100464910																																									
Name and address of owner of equipment, and its location:- Warton Freight Services Ltd, 15 Horndon Industrial Park, Station Road, West Horndon, CM13 3XL			Address where examination and test carried out if different to owner:- Warton Freight Services Ltd, 15 Horndon Industrial Park, Station Road, West Horndon, CM13 3XL, 0181 5073354																																						
Reason for Test	Commissioning ☐ LOLER Reg 6	6 Month ☐ LOLER Reg 9.3.a.(i)	12 Month ☒ LOLER Reg 9.3.a.(ii)	Overload Test ☐ BS7121 Part 2-4	Exceptional Circumstances ☐ LOLER Reg 9.3.a.(iv)																																				
<table border="0" style="width: 100%;"> <tr> <td colspan="3">Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-</td> <td colspan="3">Rated capacity (KG)</td> </tr> <tr> <td>Radius (Outreach) M</td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td>4300</td> </tr> <tr> <td>6</td> <td></td> <td></td> <td></td> <td></td> <td>2800</td> </tr> <tr> <td>8</td> <td></td> <td></td> <td></td> <td></td> <td>2050</td> </tr> <tr> <td>10</td> <td></td> <td></td> <td></td> <td></td> <td>1600</td> </tr> </table>						Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-			Rated capacity (KG)			Radius (Outreach) M						4					4300	6					2800	8					2050	10					1600
Rated capacity and load or loads and (where relevant) corresponding radii, jib lengths and counterweights:-			Rated capacity (KG)																																						
Radius (Outreach) M																																									
4					4300																																				
6					2800																																				
8					2050																																				
10					1600																																				
<table border="0" style="width: 100%;"> <tr> <td colspan="5">Details of the test or test carried out:-</td> </tr> <tr> <td>Radius (Outreach) M</td> <td>Rated Capacity (KG)</td> <td>Test Percentage</td> <td>Test Weight (KG)</td> <td>Has the Weight Been Applied</td> </tr> <tr> <td>10</td> <td>1600</td> <td>10%</td> <td>1760</td> <td>Yes</td> </tr> </table> CRANE TESTED ON FIRM LEVEL SURFACE WITH ALL OUTRIGGER LEGS FULLY DEPLOYED						Details of the test or test carried out:-					Radius (Outreach) M	Rated Capacity (KG)	Test Percentage	Test Weight (KG)	Has the Weight Been Applied	10	1600	10%	1760	Yes																					
Details of the test or test carried out:-																																									
Radius (Outreach) M	Rated Capacity (KG)	Test Percentage	Test Weight (KG)	Has the Weight Been Applied																																					
10	1600	10%	1760	Yes																																					
Identification of any part found to have a defect which is, or could become a danger to persons. The particulars of any repair, renewal or alteration required to remedy the defect either immediately or within a specified time:-																																									
Other defects and remedies:- See Thorough Examination Inspection Checklist.																																									
Observation and condition of attachment (where applicable):-																																									
Declaration:- I hereby declare that the equipment described in this record was tested, or tested and thorough examined in accordance with the Lifting Operations and Lifting Equipment Regulations (LOLER) 1998 and the above particulars are correct.																																									
Signature:-			Date the examination and test or test only carried out:- 13/12/2025																																						
Name and address of examiner / person making above declaration where applicable:-																																									
pmalinowski ALLMI Registration Number:- T H White Ltd, Nursteed Road, Devizes, Wiltshire, SN10 3EA			ALLMI Registration Number:- T H White Ltd, Trevor Foster Way, Off Chase Way, Bradford, West Yorkshire, BD5 8HB																																						
Name of person making above declaration (only to be completed if different from examiner):-																																									
ALLMI Registration Number:-																																									
Date of initial Commissioning Test:- 07/11/2019		Latest Date by which next thorough examination must be carried out:- 13/12/2026																																							
Date the record is made:- 13/12/2025		Latest Date by which next BS7121 overload test must be carried out:- 14/12/2027																																							

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890
Judgement key (J)	/ ✓ = Satisfactory / M = Monitored / R = Requires attention				

TM	Check	J
Pre-Inspection Requirements		
1.1	Equipment Clean & Ready for Inspection: No	✓
1.2	Copy of Previous Report of Thorough Examination: Yes	✓
1.3	Copy of Stability Calculation: Yes	✓
1.4	Copy of Operators Manual: Yes	✓
1.5	Record Equipment Mounting Position: Front Mount	✓
1.6	Hour Meter Reading Taken and Recorded: Yes; 981	✓
Information Plates		
2.1	SWL Plates / Decals	✓
2.2	Operator Hazard Warning Plates	✓
2.3	Equipment C E / Serial Plate	✓
Pump / PTO		
3.1	PTO Switch / Interlock	R
3.2	Air Tee / Contact Switch	✓
3.3	PTO Unit	✓
3.4	Pump	✓
3.5	Oil Tank	M
3.6	Hydraulic Oil	✓
3.7	Pressure Feed Hose	✓
3.8	High Pressure Filter	✓
3.9	Suction Hose, Clamps & Protection	✓
3.11	Power on Demand / RPM / Auto Throttle	✓
3.12	Equipment Operation	✓
Subframe / Crane Base		
4.1	Subframe Fabrication & Condition	M
4.2	Subframe C.E. Plate	✓
4.3	Side Plate / Droppers	M
4.4	Crane Base Structure	✓
4.6	Pendulum Beam	✓
4.7	Hold Down Fixings	✓
4.8	Slew Tubes	✓
4.9	Slewing System - Slew Tube Type	✓
4.10	Slewing System LHV	✓
Outrigger Legs (Including Additional Outrigger Legs if Applicable)		
5.1	Beam Structure	R
5.2	Rollers / Wear Pads	M
5.3	Cam Locks and R Clips	✓
5.5	Leg Stops	✓
5.6	Stabilizer Leg Sensors / Switches	✓
5.7	Stability Control Sensors / Switches	✓
5.8	Hoses / Pipes, Clamps & Protection	✓
5.9	Stabilizer in / out Leg Cylinder	✓
5.11	Pivoting Stabilizer Feet	✓
5.12	Stabilizer Cylinders	✓
5.13	Swing Up Stabilizer	✓
5.14	Stabilizer Operation	✓
5.15	Stabilizer Support Pads & Stowage Cage	✓

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Check	J
Valve Block(s)		
6.1	■ Dump Valve	✓
6.2	■ Valve Segment Port Relief Seals	✓
6.3	■ Overload Valve (OSK) Seals	✓
6.4	■ Main Relief Valve Seals	✓
6.5	■ Valve Block	✓
6.6	■ Control Levers / Rods	✓
6.7	■ Control Lever Decals	R
6.8	■ Additional Valve Block	✓
6.9	■ Additional Valve Block Control Levers / Rods	✓
6.10	■ Additional Valve Block Control Lever Decals	✓
6.11	■ Pressure Gauge / Fittings	✓
Column		
7.1	■ Column Structure	✓
7.2	■ Neck & Foot Bearings	✓
7.3	■ Hoses / Pipes, Clamps & Protection	✓
7.4	■ Pins / Bushes / Retainers	✓
Main (Inner) Boom Cylinder		
8.1	■ Main Boom Cylinder	✓
8.3	■ Load Hold Valve	✓
8.4	■ Pressure Transducer	✓
8.5	■ Pin / Bushes / Retainers	✓
8.6	■ Hoses / Pipes, Clamps & Protection	✓
Main (Inner) Boom		
9.1	■ Main Boom Structure	✓
9.2	■ Hoses / Pipes, Clamps & Protection	✓
9.3	■ Pins / Bushes / Retainers	✓
Jib (Outer) Boom Cylinder		
10.1	■ Outer Boom Cylinder	✓
10.3	■ Load Hold Valve	✓
10.4	■ Pins / Bushes / Retainers	✓
10.5	■ Hoses / Pipes, Clamps & Protection	✓
Outer (Jib) Boom		
11.1	■ Outer Boom Structure	✓
11.2	■ Hoses / Pipes, Clamps & Protection	✓
11.3	■ Pins / Bushes / Retainers	✓
11.5	■ Pendulum Switch	✓
Extension System		
12.1	■ Boom Structure (s)	✓
12.2	■ Cylinder(s)	✓
12.3	■ Load Hold Valve	✓
12.5	■ Cylinder Guides	✓
12.6	■ Wear Pads / Retaining Screws	M
12.7	■ Pins / Bushes	✓
12.10	■ Hoses / Pipes, Clamps & Protection	✓
12.11	■ Hose Guides / Carriers	✓
Lifting Hook		

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Check	J
13.1	■ Hook Assembly	M
13.2	■ D Shackle and Pin	✓
Safe Stowage System		
14.1	■ Boom Height Warning	✓
14.2	■ Boom Height Decal: 11 feet 6 inches	✓
14.3	■ Crane Stowage Warning	✓
14.4	■ Stabilizer Legs Stowage Warning	✓
Other Safety Equipment		
15.1	■ Leg Deployment	✓
15.2	■ Derate System	✓
15.6	■ Safety Equipment Decals	✓
15.7	■ Vehicle Level Indicators	✓
Electrics		
16.1	■ Paltronic Display	M
16.2	■ Additional Display(s)	✓
16.3	■ Additional Emergency Stop(s)	✓
16.4	■ OLP (Overload Protection) System	✓
16.5	■ Beacons	✓
16.6	■ Work Lights	R
16.7	■ Hydraulic Oil Cooler	✓
Radio Remote Control		
17.1	■ RRC Handset	✓
17.2	■ RRC Display	✓
17.3	■ RRC Operation	✓
17.4	■ RRC Active Warning Beacon	✓
17.5	■ Emergency Stop	✓
17.6	■ OLP System (Overload Protection System)	✓
17.7	■ Work Light Switch	✓
17.10	■ Warning Horn	✓
17.11	■ RRC Neck / Lap Belt	✓
17.12	■ RRC Handset Stowage System	✓
17.13	■ Programming Lead	✓
17.14	■ Decals	✓
Further Actions		
46.1	■ Service 1000 Hour Counter Reset?: Yes	✓
46.2	■ Post Weight Test Inspection Complete?: Yes	✓
46.4	■ Decal for next Service Inspection or Service Inspection and Weight Test completed?: Yes	✓
46.5	■ Pictures of Damage/Required Repairs Taken?: Yes	✓
46.6	■ Equipment Safe for Use?: Yes	✓

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890

Judgement key (J) ■ / ✓ = Satisfactory ■ / M = Monitored ■ / R = Requires attention

TM	Fault Area	Component ID	Symptom	Fault Reason	Resolution	Recommended Time Scale	Additional Comments
Non-Safety Related Defects							
3.1	Electron	Other "Suspension damp "	Inoperative	Supply	Re-prog	Repairs to be carried out before next inspection	Suspension damp not working automatically when pto engaged. Truck dealer to sort out
5.1	Gen	Other "Inspection window decal"	Missing	FWT	Repl-New	Repairs to be carried out before next inspection	Inspection window decal missing VB side
6.7	Gen	Lever Decals	Missing	FWT	Repl-New	Repairs to be carried out within 30 Days	Slew and main boom lever symbols missing
16.6	Electron	Lamp	Inoperative	FWT	Repl-New	Repairs to be carried out before next inspection	Column work light inoperative
Monitored Defects							
3.5	Hyd	Oil Tank	Coroded	FWT	Obs	Check at Next Inspection	Surface rust on tank and straps
4.1	Struc	Subframe	Coroded	FWT	Obs	Check at Next Inspection	Surface rust on subframe
4.3	Mech	Dropper	Coroded	FWT	Obs	Check at Next Inspection	Surface rust on side plates and droppers
5.2	Mech	Bottom Wear Pads	Tolerance, Worn	FWT	Obs	Check at Next Inspection	Bottom wear pads wearing thin but still serviceable
12.6	Mech	Wear Pads	Tolerance	FWT	Obs	Check at Next Inspection	Some wear to pads but still serviceable
13.1	Mech	Hook Bearing	Worn	FWT	Obs	Check at Next Inspection	Slight play in bearing but still serviceable
16.1	Electron	Front Cover	Perished	FWT	Obs	Check at Next Inspection	Main display cover cracking around buttons

Service

I hereby declare that the equipment described in this record was tested, or tested and thorough examined in accordance with the Lifting Operations and Lifting Equipment Regulations (LOLER) 1998 and the appropriate provisions and the above particulars are correct.

Job Number	SIO-123217	Vehicle Registration	EY69YSB	Operator	Warton Freight Services Ltd
Inspection Date	13/12/2025	Make / Model	PALFINGER / PK19.001ASLD5	Serial Number	100464910
Service Type	Thorough Inspection	Chassis Number	YS2P6X20009257093	Mileage	191890

Judgement key (J)  / ✓ = Satisfactory  / M = Monitored  / R = Requires attention



Name: pmalinowski

Date: 13/12/2025